1.



1. Isometric view of the lower and chamber frame
a: connection points of legs
b: connection points of linear actuator
c: hinges connecting lower and chamber frame
d: chamber (not in picture)

2.



2. Isometric view of the chamber frame. Measures are in mm.

3.



3. Overhead view of the lower frame. Measures are in mm.

4.



4. Side view of the chamber frame. Measures are in mm.